$$Q_{inv} = -C_{ox}(V_{GS} - V_T)$$
, for $V_{GS} > V_T$
 $Q_{inv} = 0$, for $V_{GS} \le V_T$