

$$J_{SHR} = \frac{qn_i x}{2\tau} (e^{V_a/2V_t} - 1)$$